

Motor Wiring

Applied Motion Products Motors

The recommended Applied Motion motors for the STAC6 include shielded cables. All of these motors should be connected in "series". Parallel connections are not suitable for the STAC6 because of the high motor bus voltage.

In most cases, the motor includes a pre-assembled connector for the STAC6. If your motor does not already have a connector attached or if you need to change the length of the cable, please follow the illustration below. Be sure to connect the cable shield for safety and to minimize electrical interference.

