



HT17

48 VDC power supply, 20000 steps/rev, all motors connected in parallel




HT23

24 VDC power supply, 20000 steps/rev, all motors connected in parallel




HT23

48 VDC power supply, 20000 steps/rev, all motors connected in parallel




HT24

24 VDC power supply, 20000 steps/rev




HT24

48 VDC power supply, 20000 steps/rev




HT34-485/486/487 with ST10

24 VDC power supply, 20000 steps/rev, all motors connected in parallel




HT34-485/486/487 with ST10

48 VDC power supply, 20000 steps/rev, all motors connected in parallel




HT34-485/486/487 with ST10

80 VDC power supply, 20000 steps/rev, all motors connected in parallel




HT34-504/505/506 with ST10

24 VDC power supply, 20000 steps/rev, all motors connected in parallel



HT34-504/505/506 with ST10

48 VDC power supply, 20000 steps/rev, all motors connected in parallel



920-0004 Rev. F
6/10/14

HT34-504/505/506 with ST10

60 VDC power supply, 20000 steps/rev, all motors connected in parallel

