



### HT24

48 VDC power supply, 20000 steps/rev




### HT34-485/486/487 with ST10

24 VDC power supply, 20000 steps/rev, all motors connected in parallel




### HT34-485/486/487 with ST10

48 VDC power supply, 20000 steps/rev, all motors connected in parallel




### HT34-485/486/487 with ST10

80 VDC power supply, 20000 steps/rev, all motors connected in parallel




### HT34-504/505/506 with ST10

24 VDC power supply, 20000 steps/rev, all motors connected in parallel



### HT34-504/505/506 with ST10

48 VDC power supply, 20000 steps/rev, all motors connected in parallel



920-0004 Rev. F  
6/10/14

### HT34-504/505/506 with ST10

60 VDC power supply, 20000 steps/rev, all motors connected in parallel

