

5014-042, STR2

Connection: 4 leads

Drive settings: 1.2A/phase, 20000 steps/rev

